

UT382

[Enlarge](#)[Download Manual](#)[Download Software](#)

Luminometers

SPECIFICATIONS

Basic Functions		Range	Best Accuracy
Illuminance Measurement	LUX	20 Lux	±(3%+20)
		200 Lux	±(3%+8)
		2000 Lux	±(3%+8)
		20000 Lux	±(3%+8)
Illuminance Measurement	CD	2CD	
		20CD	
		200CD	
		2000CD	
Special Functions			
Data Hold		Display"HOLD"	✓
Illuminance Measurement		Display "Lux/CD"	✓
Max / Min Mode		Display "Max" or " Min"	✓
Sleep Mode		Around 10 Minutes	✓
Low Battery Display		Around < 7.1V	✓
Data Logging			✓
Auto Ranging			✓
Real Time Clock			✓
Working Temperature		0°C~40°C(32°F~104°F)	✓
Deposited Temperature		-10°C~55°C(14°F~122°F)	✓
Relative Humidity		≤7.5%	✓
USB			✓

GENERAL CHARACTERISTICS

Power	9V Alkaline Battery x 1
LCD Size	22.5 x 32.5mm
Product Colour	Red and Grey
Product Net Weight	185g
Product Size	195 x 45 x 26mm
Standard Accessories	USB Interface Cable,CD, English Manual, Carrying Bag, Battery
Standard Individual Packing	Blister
Standard Quantity Per Carton	40 pcs
Standard Carton Measurement	650 x 560 x 300mm (0.11 CBM Per Standard Carton)
Standard Carton Gross Weight	15kg

*Available at Extra Cost

Specifications and other information are subject to change without further notice.

[Back to main menu](#)